


1.1 Background


In Q1, OE % is not high enough.

The Kadia Machine C is always stopping causing problems.


We decided to improve it.



1.2 Clarify the Problem - Gap



1.3 Gap Analysis



Problem to Pursue:
The Sensor on Kadia Machine C